

Product Support Bulletin 2007-008

245 W. Forest Hill Avenue Oak Creek, WI 53154

Contact: Gary D. Van Deluyster, Service Manager - Phone: 800-445-9258 - Fax: 414-766-2266

Maintenance of Way ~ Work Equipment Bulletin

DATE:	November 1	2, 2007	
SUBJECT:	Installation of additional springs in the TRIPP Rail Lifter Pressure Reducing Valve – 3601520		
RATING:	(Actio	CTIVE n is required) RMATION n is optional)	X ALERT (Potential Problem) PRODUCT IMPROVEMENT (Enhance Product)
MACHINE MODEL(S):		TRIPP Tie Remover/Inserter	
SERIAL NUMBER(S):		760125-760275	
SUMMARY:		On some machines, the Rail Lifter may rise unevenly to the Travel position. Installation of an additional spring in the Rail Lifter Pressure Reducing Valve will allow the valve to operate more consistently, reducing the tendency of the Rail Lifter to rise unevenly.	
OPERATIONAL IMPACT:		If the Rail Lifter rises unevenly, especially when it is being raised for travel, damage to the Rail Lifter LVDTs may occur. This causes the improper operation of the rail lifter during the work cycle.	
ACTION:		valve blocks and the new spri	re Cartridges must be removed from the ngs installed. The cartridges, along with w springs are reinstalled into the valve on Page 2.
WARRANTY:		Springs will be supplied under warranty for all machines s/n 760125-760275. Contact the Nordco Service Department to order your springs. Please provide the machine serial number when ordering.	




Figure 1
Rail Lift Manifold
(Viewed from Front of Machine)




Figure 2




Figure 3