

## PRODUCT SUPPORT BULLETIN BULLETIN NO. 357

DATE: July 31, 2002

MACHINE: Model C Spiker

SERIAL NUMBER(S): **410201 - 410351** 

## SUBJECT: Modify Battery Box Support

It has been reported that the Battery Box Support interferes with the changing of the RH front Brake Shoe. The Battery Box support may be chamfered 5" by 5" as shown in Figure 3. This will allow easier access to the Brake Shoe for servicing.

Please contact the NORDCO Service Department if you have any questions.



