Product Support Bulletin 2016-001



245 W. Forest Hill Avenue Oak Creek, WI 53154

Contact: Technical Support Phone: 800-445-9258 or Email: : TechSupport@Nordco.com

Maintenance of Way ~ Work Equipment Bulletin

DATE:	24 May 2016							
SUBJECT:	Propulsion Motor Upgrade Kits							
RATING:			RECTIVE tion is required)			ALERT (Potential Problem)		
		_	RMATION on is optional)		x		CT IMPROVEMEN e Product)	I T
MACHINE MODEL(S):			CX Hammer SP2R Curve Gang Spikers (CGS)					
SERIAL NUMBER(S):			All					
SUMMARY:			In some instances motor shafts do not extend all the way through the drive motor sprocket, which may cause shaft end seal failure and loose sprockets.					
OPERATIONAL IMPACT:			Less maintenance required.					
ACTION:			It is your option to purchase the upgrade kit. Repair items for original parts will remain available if you choose not to upgrade.					
WARRANTY:			None, this is a design improvement only.					
			MACHINE	ORE	ER	KIT		
		(Curve Gang Spiker	984	1800	12		