

Product Support Bulletin 2009-007


245 W. Forest Hill Avenue Oak Creek, WI 53154

Contact: Gary D. Van Deluyster, Service Manager - Phone: 800-445-9258 - Fax: 414-766-2260

Maintenance of Way ~ Work Equipment Bulletin

DATE:	June 30, 2009	
SUBJECT:	Anchor Chute Warning Plaque – 29300046	
RATING:	DIRECTIVE (Action is required)	ALERT (Potential Problem)
	X INFORMATION (Action is optional)	PRODUCT IMPROVEMENT (Enhance Product)
MACHINE MODEL(S):	BAAM	
SERIAL NUMBER(S):	690025-690055	
SUMMARY:	If the anchor chutes are not kept full of anchors, the rods of the Escapement Cylinders, p/n 28550002 or 28550003, could be bent. Plaque 29300046 will remind the operator to keep the chutes full of anchors to avoid damaging the Escapement Cylinders. See Figure 1 on Page 2.	
OPERATIONAL IMPACT:	If the Escapement Cylinder rod is bent, the cylinder will not function properly and the anchors either will not drop into the Anchor Holders or will fall out on the ground.	
ACTION:	The plaques are attached to the chutes as shown in Figure 2 on Page 2. Make sure the chute is clean and free of grease and oil. Machines with serial numbers 690056 and higher have had the Plaques installed at the factory.	
WARRANTY:	Plaques will be supplied under warranty for all listed machines if ordered before October 31, 2009. Contact the Nordco Service Department at 1-800-445-9258 to	

order. Please have the machine serial number available when ordering.



ANCHOR TRAYS/MAGAZINES MUST BE KEPT FULL AT ALL TIMES

P/N 2930 0046

Figure 1 29300046 Anchor Tray Plaque




Figure 2
Plaque installation location