

Mark II - Production and Switch Tampers

Exchange Components



Vibrator Exchanges



JV68336-02EX: Electromatic Vibrator



JE-2010512-0-02EX: Hydraulic Vibrator with Motor and Coupler

JE-2010512-0-0200EX: Hydraulic Vibrator without Motor and Coupler

Clamp Assemblies



J0-2201685-2-01: Rebuilt Roller Clamp Assembly Complete



JW683484LEX: Exchange Rail Clamp Assembly (Left)

JW683484REX: Exchange Rail Clamp Assembly (Right)

Countershaft Assembly




JX754110AEX: Exchange Rebuilt Countershaft Assembly (No Pulley)

JX754110ACEX: Exchange Rebuilt Countershaft Assembly (With Pulley)

Workhead Assemblies



JW68283-03-REX: Rebuilt Vibrator Carrier (Right)



JW68283-03-LEX: Rebuilt Vibrator Carrier (Left)

www.nordco.com

107 N. US Highway 45
PO Box 162
Arcola, IL 61910 USA
Phone: 217-268-4823

