Nordco_n Service from the Ground Up⁻

WARRANTY:

None

Product Support Bulletin 2011-005

245 W. Forest Hill Avenue Oak Creek, WI 53154

Contact: Travis Dittberner, Service Manager - Phone: 800-445-9258 - Fax: 414-766-2260

Maintenance of Way ~ Work Equipment Bulletin

DATE:	June 28th, 2011	
SUBJECT:	BAAM Workhead Cylinder Clevis Pin Upgrade Kit 98690026	
RATING:	DIRECTIVE (Action is required)	ALERT (Potential Problem)
	INFORMATION (Action is optional)	x PRODUCT IMPROVEMENT (Enhance Product)
MACHINE MODEL(S):	Anchor Applicator BAAM	
SERIAL NUMBER(S):	BAAM S/N 690025 through S/N 690071	Pivot Frame Cylinder Shoulder Bolts
SUMMARY:	A kit to upgrade the existing clevis pins on the Frame Up/Down Cylinder and the two Pivot Frame Cylinders to Grade 8 shoulder bolts is available by ordering P/N 98690026.	Management of the Park Section of the Park Sec
	Switching to the shoulder bolts will reduce possible clevis pin surface wear and provide increased shear strength in these critical locations.	
OPERATIONAL IMPACT:	NONE	
ACTION:	Customer install would be required and LOTO procedures should be followed during installation. Allow approximately 1 hour for installation.	