

Product Support Bulletin 2011-008

245 W. Forest Hill Avenue Oak Creek, WI 53154

Contact: Travis Dittberner, Service Manager - Phone: 800-445-9258 - Fax: 414-766-2260

Maintenance of Way ~ Work Equipment Bulletin

DATE:	June 28th, 2011
SUBJECT:	Guide Rod Auto-Oiler Kit P/N 98410489
RATING:	DIRECTIVEALERT(Action is required)(Potential Problem)
	INFORMATION (Action is optional)xPRODUCT IMPROVEMENT (Enhance Product)
MACHINE MODEL(S):	CX Hammers C-CX Hammer Conversions 99C Spikers
SERIAL NUMBER(S):	CX Hammer S/N 410500-410898, 410906-410950, 410954-410955, and 410958-410961 C-CX Conversion, all except S/N410111RB-UG, 410215RB-UG, and 410220RB-UG-4102223RB-UG
SUMMARY:	 A kit has been developed that automatically lubes the guide rod bushings, thereby increasing bushing life. Kit 98410489 includes all parts necessary as well as installation instructions. Some welding is required. Replacement oil containers are available by ordering P/N 3805250-630.
OPERATIONAL IMPACT:	None
ACTION:	Customer install would be required. Allow approximately 8 hours for installation on all four guns.
WARRANTY:	None