Product Support Bulletin 2015-003



WARRANTY:

245 W. Forest Hill Avenue Oak Creek, WI 53154


Contact: Technical Support Phone: 800-445-9258 or Email: TechSupport@Nordco.com

Maintenance of Way ~ Work Equipment Bulletin

DATE:	August 24,							
SUBJECT:	Rail Lift Cylinder Attachment Pin and Keeper Kit - 98760138							
RATING:	(Actio	CTIVE n is required) RMATION n is optional)	□	ALERT (Potential Problem) PRODUCT IMPROVEMENT (Enhance Product)				
MACHINE MODEL(S):		TRIPP Models A,B,C and D						
SERIAL NUMBER(S):		All						
SUMMARY:		retention design announced u	under	hment flag style pins and bow tie Product Support Bulletin 2007-002 pin and keeper bar design. (See				
OPERATIONA	L IMPACT:	The rail lift cylinder pins are now more rigidly retained. This new design prevents the cylinder attachment pins from moving out of position.						
ACTION:		bowtie clip mounting pins ca and Rail Lift Frame, or remove Two holes will have to be accommodate the Pin Keeper w/Keeper Slot. After holes a w/Keeper Slot is inserted and with the slot on the Pin and the typical installation. One kit, components required to compapproximately 2-3 hours per many	n eith red (g drille Bar di are di d inde e tapp see lete o nachin					
		Please contact your NORDCon Department 1-800-647-1724 for		presentative or the NORDCO Parts additional assistance.				

Page 1 of 2
Please Turn the Page

None



NORDCO Product Support Bulletin 2015-003




TABLE 1 - LIFT PIN KIT

KIT P/N 98760138								
BILL OF MATERIALS								
ITEM NO.	PART NUMBER OR MATERIAL	QTY. REQ.	D T L	PART NAME	DWG SIZE			
1	54268446	4		LIFT PIN w/ KEEPER SLOT				
2	13172423	4		PIN KEEPER BAR				
3	3065916	8		1/2 LOCKWASHER				
4	2775291	8		1/2 x 1-1/4 BOLT				
5	63892045	2		RING SPACER				
6	86041342	2		PIN RETAING WASHER				
7	3064482	2		5/8 LOCKWASHER				
8	2775801	2		5/8 x 1-1/2 BOLT				
9	97765081DWG	1		KIT INSTALL DRAWING				

http://www.nordco.com/Customer-Support/Maintenance-of-Way-Equipment/Product-Support-Bulletins.htm